

check EGOT

## Non-Problems

It should be mention the following items/issues were not a problem originally + were closely watched to ensure that were not a problem after mods

Clinkers

formation + A pendents

waterwall tube wastage

reducing atmosphere corrosion of furnace water walls

boiler tube samples exterior corrosion rates

Stan/Denis  
Copres reports